



COLIN CONSTRUCTION COMPANY

DESIGN **BUILD** FOR HEALTH **CARE**



THE CLIENT SAID...

Sonora Regional Diagnostic Imaging Center Sonora, CA

DELIVERY METHOD: Design Build

COMPLETION DATE: 2007 December

A 9,375-square-foot remodel of existing office building to accommodate a diagnostic imaging center for Sonora Regional. Included a complete demolition of existing interior. Added structural concrete to allow for increased loads by the new equipment. Added exterior concrete for sidewalks and electrical/HVAC equipment. Reframed all interior walls to match new layout. Installed new doors and storefront. Installed all new finishes and casework to match the interior designer's schedule. Project included ADA features in the restrooms and throughout the building. Added new HVAC to properly condition the building and cool the equipment. Upsized existing electrical service and installed a power conditioner.

Highlights

- Colin Construction's delivery of this project allowed the centrally located Center to provide local residents the option to receive healthcare based on quality medical services, technology, support systems, and compassionate staff in a state-of-the-art medical center, not based on the location of the hospital.
- The imaging center was designed to provide a calm, warm, and friendly atmosphere designed to help patients feel comfortable and secure.